



Micron Technology, Inc.  
8000 S. Federal Way  
PO Box 6  
Boise, ID United States

4GB v4.41 (J54U/J54K), v4.51 (J54K) & v5.0 (J54A ) 153B WT e.MMC end of Life (EOL) & Migration to high performance v5.0 J54A

PCN: 31713

Published: 2015-10-30

<b>Type:</b>	End of Life, New Product Intro
<b>Description:</b>	4GB 153B Wireless Temp e.MMC products (J54U, J54K & J54A) will end of life with a migration path to new high performance 4GB v5.0 J54A solution
<b>Reason:</b>	Better Align With Industry Standard
<b>Product Affected:</b>	4GB e.MMC J54U, J54K, & J54A 153B Wireless Temp products

Affected Micron Part Number Component	Recommended Replacement	Customer Part Number
MTFC4GACAEAM-1M WT	MTFC4GACAJCN-1M WT	
<b>MTFC4GACAECN-1M WT</b>	<b>MTFC4GACAJCN-1M WT</b>	
<b>MTFC4GLDEA-0M WT</b>	<b>MTFC4GACAJCN-1M WT</b>	
MTFC4GMCAM-1M WT	MTFC4GACAJCN-1M WT	
<b>MTFC4GMCDM-1M WT</b>	<b>MTFC4GACAJCN-1M WT</b>	
<b>MTFC4GMDEA-1M WT</b>	<b>MTFC4GACAJCN-1M WT</b>	

\*Materials that have been ordered are in **bold**.

<b>Method of Identification:</b>	Material Product Number (MPN)
<b>Micron Sites Affected:</b>	All Sites
<b>Sample Available:</b>	2015-10-05
<b>Qual Data Available:</b>	2016-01-18
<b>Last Purchase Date*:</b>	2016-06-17
<b>Last Shipment Date:</b>	2016-12-19

*\*Orders placed prior to the last purchase date are subject to current inventory levels, which may vary based on market conditions and customer demand. Early orders are encouraged.*

*NOTE: Per JEDEC Standard JESD46-C Section 3.2.3; lack of acknowledgment of this PCN within 30 days constitutes acceptance of change.*

**Micron Confidential and Proprietary Information**

Thank you

Legal Disclaimer: The information contained in this message may be privileged and confidential. It is intended to be read only by the individual or entity to whom it is addressed or by their designee. If the reader of this message is not the intended recipient, you are on notice that any distribution of this message, in any form, is strictly prohibited. If you have received this message in error, please immediately notify the sender and delete or destroy any copy of this message.