

**Dear Customer,**

With this INFINEON Technologies Information Note we would like to inform you about the following

**Datasheet update affecting products TLE5012B\***

N° 047/18

## Datasheet update affecting products TLE5012B\*

► **Products affected:**

Please refer to attached affected product list 1\_cip04718

► **Detailed Change Information:**

**Subject:** Datasheet update

**Reason:** Datasheet update due minor changes of:  
- New Template/New Logo  
- Chapter4.4.5: Add footnote regarding maximum rotation speed  
- Chapter3: Update

**Description:**

Old

- Revision 2.0

New

- Revision 2.1  
for details please refer to  
datasheet (4\_cip04718)  
attached

► **Product Identification:**

Not applicable (no change of product)

► **Impact of Change:**

No impact expected because of minor changes only.

► **Attachments:**

1\_cip04718 Affected product list  
4\_cip04718 Datasheet

► **Intended start of delivery:**

Not applicable

If you have any questions, please do not hesitate to contact your local Sales office.

INF N°047/18

Datasheet update affecting products TLE5012B\*



Sales Name	SP number	OPN	Package
TLE5012B E1000	SP000905682	TLE5012BE1000FUMA1	PG-DSO-8-16
TLE5012B E1000	SP001166960	TLE5012BE1000XUMA1	PG-DSO-8-16
TLE5012B E3005	SP000905686	TLE5012BE3005FUMA1	PG-DSO-8-16
TLE5012B E3005	SP001166964	TLE5012BE3005XUMA1	PG-DSO-8-16
TLE5012B E5000	SP000905690	TLE5012BE5000FUMA1	PG-DSO-8-16
TLE5012B E5000	SP001166968	TLE5012BE5000XUMA1	PG-DSO-8-16
TLE5012B E5020	SP001166972	TLE5012BE5020XUMA1	PG-DSO-8-16
TLE5012B E9000	SP000905694	TLE5012BE9000FUMA1	PG-DSO-8-16
TLE5012B E9000	SP001166998	TLE5012BE9000XUMA1	PG-DSO-8-16
TLE5012BD E1200	SP001205296	TLE5012BDE1200XUMA1	PG-TDSO-16-2
TLE5012BD E9200	SP001205300	TLE5012BDE9200XUMA1	PG-TDSO-16-2