



## Product Change Notification / SYST-14GPBA174

---

### Date:

18-Apr-2022

### Product Category:

Ethernet Bridges

### PCN Type:

Document Change

### Notification Subject:

Data Sheet - LAN7801 - SuperSpeed USB 3.1 Gen 1 10/100/1000 Ethernet Controller with RGMII Data Sheet Document Revision

### Affected CPNs:

[SYST-14GPBA174\\_Affected\\_CPN\\_04182022.pdf](#)  
[SYST-14GPBA174\\_Affected\\_CPN\\_04182022.csv](#)

### Notification Text:

SYST-14GPBA174

Microchip has released a new Product Documents for the LAN7801 - SuperSpeed USB 3.1 Gen 1 10/100/1000 Ethernet Controller with RGMII of devices. If you are using one of these devices please read the document located at [LAN7801 - SuperSpeed USB 3.1 Gen 1 10/100/1000 Ethernet Controller with RGMII](#).

**Notification Status:** Final

**Description of Change:** 1. Figure 16-1, "64-SQFN Package (Drawing)", Figure 16-2, "64-SQFN Package (Dimensions)": Updated the package code from "R4" to "9JX"

**Impacts to Data Sheet:** See above details.

**Reason for Change:** To Improve Productivity

**Change Implementation Status:** Complete

**Date Document Changes Effective:** 18 April 2022

**NOTE:** Please be advised that this is a change to the document only the product has not been changed.

**Markings to Distinguish Revised from Unrevised Devices:** N/A

## **Attachments:**

**LAN7801 - SuperSpeed USB 3.1 Gen 1 10/100/1000 Ethernet Controller with RGMII**

Please contact your local **Microchip sales office** with questions or concerns regarding this notification.

## **Terms and Conditions:**

If you wish to receive Microchip PCNs via email please register for our PCN email service at our **PCN home page** select register then fill in the required fields. You will find instructions about registering for Microchips PCN email service in the **PCN FAQ** section.

If you wish to change your PCN profile, including opt out, please go to the **PCN home page** select login and sign into your myMicrochip account. Select a profile option from the left navigation bar and make the applicable selections.

Affected Catalog Part Numbers (CPN)

LAN7801/9JX

LAN7801-I/9JX

LAN7801-I/9JXVAO

LAN7801-V/9JXVAO

LAN7801T-V/9JXVAO

LAN7801T/9JX

LAN7801T-I/9JX

LAN7801T-I/9JXVAO