



Product Change Notification

TE Connectivity

Product Change Notification: P-16-013119

PCN Date: 06-JUN-16

TE would like to inform you of the following change(s) to the listed TE Connectivity Product. In case of any further questions about this change(s), please contact your TE Connectivity Sales Engineer. Affected part, drawing and/or specification numbers are listed on the attached sheet(s).

General Product Description:

MSR/V23061 Change of packaging

Description of Changes

In order to improve the packaging of the MSR/V23061, the size of the shipper box will be reduced. The number of relays per box will be changed from 1000pcs/box to 500pcs/box. The new box will be made out of stronger corrugated cardboard and is approved according TE standard. The product itself remains unchanged.

Reason for Changes:

Product improvement.

Estimated Dates:

Last Order Date (Obsolete Parts Only): First Date To Ship (Changed Parts Only):

01-JUL-2016

Last Ship Date (Obsolete Parts Only): Last Date for Mixed Shipments: (Changed Parts Only):

No Mixed Shipments

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
1-1393222-5	NO			"V23061A1004A302"			
1-1393223-2	NO			"V23061B1006A401"			
1393222-4	NO			"V23061A1002A302"			
1393223-3	NO			"T75S5D112-12", "V23061B1005X 6"			
2-1393222-7	NO			"V23061A1005A502"			
2-1393223-1	NO			"V23061B1007A401"			
2-1393223-5	NO			"V23061B1007A501"			
2-1393223-8	NO			"T75S5D112-24", "V23061B1007X 8"			
3-1393222-9	NO			"V23061A1007A302"			
4-1393223-1	NO			"T75S5D112-48", "V23061B1009X 10", "V23061B1009X010"			
7-1393222-4	NO			"V23061B1002A501"			
7-1393222-5	NO			"V23061B1002A601"			
7-1393222-6	NO			"T75S5D112-05", "V23061B1002X 3"			
9-1393222-1	NO			"V23061B1005A301"			
9-1393222-4	NO			"V23061B1005A401"			
9-1393222-7	NO			"V23061B1005A501"			

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
4-1393223-1	NO			"T75S5D112-48", "V23061B1009X 10", "V23061B1009X010"			

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
1-1393223-2	NO			"V23061B1006A401"			
1393222-4	NO			"V23061A1002A302"			
1393223-3	NO			"T75S5D112-12", "V23061B1005X 6"			
2-1393222-7	NO			"V23061A1005A502"			
2-1393223-1	NO			"V23061B1007A401"			
2-1393223-5	NO			"V23061B1007A501"			
3-1393222-9	NO			"V23061A1007A302"			
7-1393222-4	NO			"V23061B1002A501"			
7-1393222-5	NO			"V23061B1002A601"			
7-1393222-6	NO			"T75S5D112-05", "V23061B1002X 3"			
9-1393222-1	NO			"V23061B1005A301"			
9-1393222-4	NO			"V23061B1005A401"			
9-1393222-7	NO			"V23061B1005A501"			

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
1-1393222-5	NO			"V23061A1004A302"			
1393223-3	NO			"T75S5D112-12", "V23061B1005X 6"			
2-1393223-8	NO			"T75S5D112-24", "V23061B1007X 8"			
4-1393223-1	NO			"T75S5D112-48", "V23061B1009X 10", "V23061B1009X010"			
7-1393222-6	NO			"T75S5D112-05", "V23061B1002X 3"			

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
1-1393222-5	NO			"V23061A1004A302"			
1393223-3	NO			"T75S5D112-12", "V23061B1005X 6"			
2-1393223-8	NO			"T75S5D112-24", "V23061B1007X 8"			
4-1393223-1	NO			"T75S5D112-48", "V23061B1009X 10", "V23061B1009X010"			
7-1393222-6	NO			"T75S5D112-05", "V23061B1002X 3"			