

End Of Life Notice
(Notification – PLC19018
[31 May 2019])

To: Our Valued Customers

Overview: The purpose of this notification is to communicate that Renesas Electronics has begun the End-of-Life (EOL) Process on select part numbers.

Affected

Products: Attached is a list of products affected by this notification.

Part numbers given in the attached list are for active part numbers in the Renesas Electronics database at the time of this notification.

Key Dates:

| Standard Product | |
|---|------------------|
| Final Last Time Buy (LTB) Orders placed after this date will not be processed. | 30-Nov-19 |
| Last Shipment (LTS) | 30-May-20 |
| Custom / Proprietary Product | |
| Final Last Time Buy (LTB) Orders placed after this date will not be processed. | 31-May-20 |
| Last Shipment (LTS) | 30-Nov-20 |

Response: Please place LTB orders in a timely manner prior to the key dates listed to avoid product availability issues. Shipments between the LTB and LTS dates are Non-Cancelable and Non-Returnable (NCNR).

Renesas Electronics America Inc. will attempt to honor all such purchase orders and scheduled delivery dates, but reserves the right to not accept new orders or to cancel existing orders if such orders cannot be filled through reasonable commercial effort.

Any order resulting from this notice shall be governed by Renesas's General Terms and Conditions Available at: [General Term and Conditions](#) or the applicable legal terms covering the purchase and sale transaction.

Please work with your sales representative or Field Applications Engineer to determine suitable replacement devices.

Please contact your local sales representative or Central Applications @ 1-888-468-3774 for any questions or comments.

Thank you for your attention.

Sincerely,
Renesas Electronics

| Exact Renesas Part # No other variation is being impacted. | Notice PLC19018 Issue Date | LTB / Withdrawn Date | LTS / Obsolete Date | Replacement / Similar / Re-Design |
|--|----------------------------|----------------------|---------------------|-----------------------------------|
| 5962-89635012A | 31-May-19 | 30-Nov-19 | 30-May-20 | none |
| 5962-8963501PA | 31-May-19 | 30-Nov-19 | 30-May-20 | none |
| EL5373IUZ | 31-May-19 | 31-May-20 | 30-Nov-20 | none |
| EL5373IUZR5293-T7 | 31-May-19 | 31-May-20 | 30-Nov-20 | none |
| EL5373IUZ-T13 | 31-May-19 | 31-May-20 | 30-Nov-20 | none |
| EL5373IUZ-T7 | 31-May-19 | 31-May-20 | 30-Nov-20 | none |
| EL9115ILZR5504 | 31-May-19 | 30-Nov-19 | 30-May-20 | EL9115ILZ-T13 |
| EL9115ILZS2714 | 31-May-19 | 30-Nov-19 | 30-May-20 | EL9115ILZ-T13 |
| EL9115ILZ-T7R5504 | 31-May-19 | 30-Nov-19 | 30-May-20 | EL9115ILZ-T13 |
| EL9115ILZ-T7R5556 | 31-May-19 | 30-Nov-19 | 30-May-20 | EL9115ILZ-T13 |
| EL9115ILZ-T7S2714 | 31-May-19 | 30-Nov-19 | 30-May-20 | EL9115ILZ-T13 |
| HA1-4905-5 | 31-May-19 | 31-May-20 | 30-Nov-20 | none |
| HA7-5101/883 | 31-May-19 | 30-Nov-19 | 30-May-20 | none |
| HA9P4905-5Z | 31-May-19 | 31-May-20 | 30-Nov-20 | none |
| HAA0-51042R4191 | 31-May-19 | 30-Nov-19 | 30-May-20 | none |
| HAA9-50795R4814 | 31-May-19 | 30-Nov-19 | 30-May-20 | none |
| ICL3241CAZ-TS2705 | 31-May-19 | 29-Feb-20 | 29-Aug-20 | ICL3241EIVZ-T |
| ICL3244ECAZ-TS2705 | 31-May-19 | 29-Feb-20 | 29-Aug-20 | ICL3244EIAZ-T |
| ISL1591IRTZ-T13R5839 | 31-May-19 | 30-Nov-19 | 30-May-20 | none |
| ISL1591IRTZ-T7R5839 | 31-May-19 | 30-Nov-19 | 30-May-20 | none |
| ISL28022FUZR5453 | 31-May-19 | 31-May-20 | 30-Nov-20 | none |
| ISL28107FUZ-T13 | 31-May-19 | 31-May-20 | 30-Nov-20 | none |
| ISL28107FUZ-T13S2568 | 31-May-19 | 30-Nov-19 | 30-May-20 | none |
| ISL28248FUZ | 31-May-19 | 31-May-20 | 30-Nov-20 | none |
| ISL28248FUZ-T7 | 31-May-19 | 31-May-20 | 30-Nov-20 | none |
| ISL28288EVAL1Z | 31-May-19 | 30-Nov-19 | 30-May-20 | none |
| ISL28288FBZ | 31-May-19 | 31-May-20 | 30-Nov-20 | none |
| ISL28288FBZ-T7 | 31-May-19 | 31-May-20 | 30-Nov-20 | none |
| ISL28288FUZ | 31-May-19 | 31-May-20 | 30-Nov-20 | none |
| ISL28288FUZ-T7 | 31-May-19 | 31-May-20 | 30-Nov-20 | none |
| ISL28488EVAL1Z | 31-May-19 | 30-Nov-19 | 30-May-20 | none |
| ISL28488FVZ | 31-May-19 | 30-Nov-19 | 30-May-20 | none |
| ISL28488FVZ-T7 | 31-May-19 | 30-Nov-19 | 30-May-20 | none |
| ISL53514AWS2571 | 31-May-19 | 30-Nov-19 | 30-May-20 | none |
| ISL59445IRZ | 31-May-19 | 31-May-20 | 30-Nov-20 | none |
| ISL59445IRZ-T7 | 31-May-19 | 31-May-20 | 30-Nov-20 | none |
| ISL59920IRZ | 31-May-19 | 31-May-20 | 30-Nov-20 | EL9115ILZ |

| Exact Renesas Part # No other variation is being impacted. | Notice PLC19018 Issue Date | LTB / Withdrawn Date | LTS / Obsolete Date | Replacement / Similar / Re-Design |
|--|----------------------------|----------------------|---------------------|-----------------------------------|
| ISL59920IRZ-T7 | 31-May-19 | 31-May-20 | 30-Nov-20 | EL9115ILZ-T7 / EL9115ILZ-T13 |
| ISL6443AEVAL2Z | 31-May-19 | 30-Nov-19 | 30-May-20 | none |
| ISL6443AIRZ | 31-May-19 | 31-May-20 | 30-Nov-20 | none |
| ISL6443AIRZ-TK | 31-May-19 | 31-May-20 | 30-Nov-20 | none |
| ISL6443IRZ | 31-May-19 | 31-May-20 | 30-Nov-20 | none |
| ISL6443IRZ-T | 31-May-19 | 31-May-20 | 30-Nov-20 | none |
| ISL6443IRZ-TK | 31-May-19 | 31-May-20 | 30-Nov-20 | none |
| ISL6720AARZ | 31-May-19 | 31-May-20 | 30-Nov-20 | none |
| ISL6841EVAL3Z | 31-May-19 | 30-Nov-19 | 30-May-20 | none |
| ISL6841IUZ | 31-May-19 | 30-Nov-19 | 30-May-20 | ISL8841AAUZ |
| ISL6841IUZ-T | 31-May-19 | 30-Nov-19 | 30-May-20 | ISL8841AAUZ-T |
| ISL8215MEVAL1Z | 31-May-19 | 31-May-19 | 31-May-19 | ISL8215MEVAL2Z |
| ISL8560MREP | 31-May-19 | 30-Nov-19 | 30-May-20 | none |
| ISL8560MREP-TK | 31-May-19 | 30-Nov-19 | 30-May-20 | none |
| ISL9220AIRTZ-T | 31-May-19 | 31-May-20 | 30-Nov-20 | none |
| ISL9220AIRTZ-T7A | 31-May-19 | 31-May-20 | 30-Nov-20 | none |
| ISL9220IRTZEVAL1Z | 31-May-19 | 30-Nov-19 | 30-May-20 | none |
| ISL9220IRTZ-T | 31-May-19 | 31-May-20 | 30-Nov-20 | none |
| ISL9220IRTZ-T7A | 31-May-19 | 31-May-20 | 30-Nov-20 | none |
| ISL9220IRTZ-T7AS2758 | 31-May-19 | 30-Nov-19 | 30-May-20 | none |
| ISL95810UIRT8Z | 31-May-19 | 31-May-20 | 30-Nov-20 | none |
| ISL95810UIRT8Z-T | 31-May-19 | 31-May-20 | 30-Nov-20 | none |
| ISL95816HRZ | 31-May-19 | 31-May-20 | 30-Nov-20 | none |
| ISL95816HRZ-T | 31-May-19 | 31-May-20 | 30-Nov-20 | none |
| ISL95818HRTZ | 31-May-19 | 30-Nov-19 | 30-May-20 | none |
| ISL95818HRTZ-T | 31-May-19 | 30-Nov-19 | 30-May-20 | none |
| ISL95818IRTZ | 31-May-19 | 30-Nov-19 | 30-May-20 | none |
| ISL95818IRTZ-T | 31-May-19 | 30-Nov-19 | 30-May-20 | none |
| JM38510/12203BGA | 31-May-19 | 30-Nov-19 | 30-May-20 | none |
| TW8807-LA2-GR | 31-May-19 | 31-May-20 | 30-Nov-20 | none |
| TW8816-LA3-GRR5438 | 31-May-19 | 30-Nov-19 | 30-May-20 | TW8816-LA3-GRS |
| TW8817-TA6-GRSHT | 31-May-19 | 30-Nov-19 | 30-May-20 | none |
| TW8827-TA3-GR | 31-May-19 | 31-May-20 | 30-Nov-20 | none |
| TW9903-MBS | 31-May-19 | 31-May-20 | 30-Nov-20 | none |
| TW9907-TA1-GR | 31-May-19 | 31-May-20 | 30-Nov-20 | none |
| TW9920-BC1-GR | 31-May-19 | 31-May-20 | 30-Nov-20 | none |

| Exact Renesas Part # No other variation is being impacted. | Notice PLC19018 Issue Date | LTB / Withdrawn Date | LTS / Obsolete Date | Replacement / Similar / Re-Design |
|--|----------------------------|----------------------|---------------------|-----------------------------------|
| X9313WPIZ | 31-May-19 | 31-May-20 | 30-Nov-20 | none |
| X9318WP8IZ | 31-May-19 | 31-May-20 | 30-Nov-20 | none |
| X9319WS8IZ | 31-May-19 | 31-May-20 | 30-Nov-20 | none |
| X9319WS8IZT1 | 31-May-19 | 31-May-20 | 30-Nov-20 | none |
| X9319WS8Z | 31-May-19 | 31-May-20 | 30-Nov-20 | none |
| X9319WS8ZT1 | 31-May-19 | 31-May-20 | 30-Nov-20 | none |
| X9400WS24IZ | 31-May-19 | 31-May-20 | 30-Nov-20 | none |
| X9400WS24IZ-2.7 | 31-May-19 | 31-May-20 | 30-Nov-20 | none |
| X9400WS24IZ-2.7T1 | 31-May-19 | 31-May-20 | 30-Nov-20 | none |
| X9400WS24IZT1 | 31-May-19 | 31-May-20 | 30-Nov-20 | none |
| X9400WS24IZT1S2705 | 31-May-19 | 29-Feb-20 | 29-Aug-20 | none |
| X9400WV24IZ | 31-May-19 | 31-May-20 | 30-Nov-20 | none |
| X9400WV24IZT1 | 31-May-19 | 31-May-20 | 30-Nov-20 | none |
| X9408WS24IZ-2.7 | 31-May-19 | 31-May-20 | 30-Nov-20 | none |
| X9408WS24IZ-2.7T2 | 31-May-19 | 31-May-20 | 30-Nov-20 | none |
| X9408WV24IZ | 31-May-19 | 31-May-20 | 30-Nov-20 | none |
| X9408WV24IZ-2.7 | 31-May-19 | 31-May-20 | 30-Nov-20 | none |
| X9408WV24IZ-2.7T1 | 31-May-19 | 31-May-20 | 30-Nov-20 | none |
| X9408WV24IZT1 | 31-May-19 | 31-May-20 | 30-Nov-20 | none |
| X9408WV24Z | 31-May-19 | 31-May-20 | 30-Nov-20 | none |
| X9408WV24Z-2.7 | 31-May-19 | 31-May-20 | 30-Nov-20 | none |
| X9408WV24Z-2.7T1 | 31-May-19 | 31-May-20 | 30-Nov-20 | none |
| X9408WV24ZT1 | 31-May-19 | 31-May-20 | 30-Nov-20 | none |
| X9408WW | 31-May-19 | 30-Nov-19 | 30-May-20 | none |
| X9C102PZ | 31-May-19 | 30-Nov-19 | 30-May-20 | none |
| X9C104PIZ | 31-May-19 | 31-May-20 | 30-Nov-20 | none |
| X9C303PIZ | 31-May-19 | 31-May-20 | 30-Nov-20 | none |
| X9C303PZ | 31-May-19 | 31-May-20 | 30-Nov-20 | none |
| X9C303S8IZ | 31-May-19 | 31-May-20 | 30-Nov-20 | none |
| X9C303S8IZ-2.7 | 31-May-19 | 31-May-20 | 30-Nov-20 | none |
| X9C303S8IZT1 | 31-May-19 | 31-May-20 | 30-Nov-20 | none |
| X9C303S8Z | 31-May-19 | 31-May-20 | 30-Nov-20 | none |
| X9C303S8ZT1 | 31-May-19 | 31-May-20 | 30-Nov-20 | none |
| X9C303V8IZ | 31-May-19 | 31-May-20 | 30-Nov-20 | none |
| X9C303V8IZT1 | 31-May-19 | 31-May-20 | 30-Nov-20 | none |
| X9C303V8ZT1 | 31-May-19 | 31-May-20 | 30-Nov-20 | none |
| X9C503PIZ | 31-May-19 | 30-Nov-19 | 30-May-20 | none |

| Exact Renesas Part # No other variation is being impacted. | Notice PLC19018 Issue Date | LTB / Withdrawn Date | LTS / Obsolete Date | Replacement / Similar / Re-Design |
|--|----------------------------|----------------------|---------------------|-----------------------------------|
| X9C503PZ | 31-May-19 | 30-Nov-19 | 30-May-20 | none |
| ZLUSBEVAL3Z | 31-May-19 | 31-May-19 | 31-May-19 | ISLUSBEVAL1Z |