

**Dear Customer,**

With this INFINEON Technologies Information Note we would like to inform you about the following

## **Datasheet update for CAN Transceiver and SBC**

N° 102/19

## Datasheet update for CAN Transceiver and SBC

► **Products affected:**

Please refer to attached affected product list 1\_cip10219

► **Detailed Change Information:**

**Subject:** Datasheet update for CAN Transceiver and SBC

**Reason:** Datasheet update to include Vdiff slope parameters

**Description:**

**Datasheet revision**

Old

- TLE926x(-3)BQX (V33): Rev 1.0
- TLE9271/2/3QX (V33): Rev 1.4
- TLE9278(-3)BQX (V33): Rev 1.4
- TLE9461(-3)ES (V33): Rev 1.0
- TLE9471(-3)ES (V33): Rev 1.0
- TLE9250(V,X)x: Rev 1.1
- TLE9251(V)x: Rev 1.1
- TLE9252V: Rev 1.1

New

- TLE926x(-3)BQX (V33): Rev 1.1
- TLE9271/2/3QX (V33): Rev 1.5
- TLE9278(-3)BQX (V33): Rev 1.5
- TLE9461(-3)ES (V33): Rev 1.1
- TLE9471(-3)ES (V33): Rev 1.1
- TLE9250(V,X)x: Rev 1.11
- TLE9251(V)x: Rev 1.11
- TLE9252V: Rev 1.11

► **Product Identification:**

not applicable

► **Impact of Change:**

No changes applied on product level.

► **Attachments:**

1\_cip10219 affected product list  
3\_cip10219 datasheet updates

► **Intended start of delivery:**

2019-November-15

If you have any questions, please do not hesitate to contact your local Sales office.



Sales name	SP number	OPN	Package
TLE9250LE	SP001631572	TLE9250LEXUMA1	PG-TSON-8
TLE9250SJ	SP001358154	TLE9250SJXUMA1	PG-DSO-8
TLE9250VLE	SP001631590	TLE9250VLEXUMA1	PG-TSON-8
TLE9250VSJ	SP001358156	TLE9250VSJXUMA1	PG-DSO-8
TLE9250XLE	SP001631594	TLE9250XLEXUMA1	PG-TSON-8
TLE9250XSJ	SP001358158	TLE9250XSJXUMA1	PG-DSO-8
TLE9251LE	SP001987446	TLE9251LEXUMA1	PG-TSON-8
TLE9251SJ	SP001825552	TLE9251SJXUMA1	PG-DSO-8
TLE9251VLE	SP001631598	TLE9251VLEXUMA1	PG-TSON-8
TLE9251VSJ	SP001358162	TLE9251VSJXUMA1	PG-DSO-8
TLE9252VLC	SP001619730	TLE9252VLCXUMA1	PG-TSON-14
TLE9252VSK	SP001619734	TLE9252VSKXUMA1	PG-DSO-14
TLE9261-3BQX	SP001611010	TLE92613BQXXUMA1	PG-VQFN-48
TLE9261-3BQX V33	SP001611060	TLE92613BQXV33XUMA1	PG-VQFN-48
TLE9261BQX	SP001611020	TLE9261BQXXUMA1	PG-VQFN-48
TLE9261BQX V33	SP001611024	TLE9261BQXV33XUMA1	PG-VQFN-48
TLE9262-3BQX	SP001611028	TLE92623BQXXUMA1	PG-VQFN-48
TLE9262-3BQX V33	SP001611032	TLE92623BQXV33XUMA1	PG-VQFN-48
TLE9262BQX	SP001611036	TLE9262BQXXUMA1	PG-VQFN-48
TLE9262BQX V33	SP001611056	TLE9262BQXV33XUMA1	PG-VQFN-48
TLE9263-3BQX	SP001611040	TLE92633BQXXUMA1	PG-VQFN-48
TLE9263-3BQX V33	SP001611044	TLE92633BQXV33XUMA1	PG-VQFN-48
TLE9263BQX	SP001611048	TLE9263BQXXUMA1	PG-VQFN-48
TLE9263BQX V33	SP001611052	TLE9263BQXV33XUMA1	PG-VQFN-48
TLE9271QX	SP000953180	TLE9271QXXUMA1	PG-VQFN-48
TLE9271QX V33	SP001078102	TLE9271QXV33XUMA1	PG-VQFN-48
TLE9272QX	SP000953178	TLE9272QXXUMA1	PG-VQFN-48
TLE9272QX V33	SP001078104	TLE9272QXV33XUMA1	PG-VQFN-48
TLE9273QX	SP000953056	TLE9273QXXUMA1	PG-VQFN-48
TLE9273QX V33	SP001078106	TLE9273QXV33XUMA1	PG-VQFN-48
TLE9278-3BQX	SP001833648	TLE92783BQXXUMA1	PG-VQFN-48
TLE9278-3BQX V33	SP001833644	TLE92783BQXV33XUMA1	PG-VQFN-48
TLE9278BQX	SP001833640	TLE9278BQXXUMA1	PG-VQFN-48
TLE9278BQX V33	SP001833636	TLE9278BQXV33XUMA1	PG-VQFN-48
TLE9461-3ES	SP001480524	TLE94613ESXUMA1	PG-TSDSO-24
TLE9461-3ES V33	SP001480520	TLE94613ESV33XUMA1	PG-TSDSO-24

TLE9461ES	SP001480534	TLE9461ESXUMA1	PG-TSDSO-24
TLE9461ES V33	SP001480528	TLE9461ESV33XUMA1	PG-TSDSO-24
TLE9471-3ES	SP001480544	TLE94713ESXUMA1	PG-TSDSO-24
TLE9471-3ES V33	SP001480540	TLE94713ESV33XUMA1	PG-TSDSO-24
TLE9471ES	SP001480552	TLE9471ESXUMA1	PG-TSDSO-24
TLE9471ES V33	SP001480548	TLE9471ESV33XUMA1	PG-TSDSO-24