

Product Change Notification - SYST-26QJTU670

Date:

27 Apr 2018

Product Category:

Development Tools; Ethernet PHYs

Affected CPNs:**Notification subject:**

Data Sheet - LAN8810/LAN8810i - GMII 10/100/1000 Ethernet Transceiver w/HP Auto-MDIX Support Data Sheet Document Revision

Notification text:

SYST-26QJTU670

Microchip has released a new DeviceDoc for the LAN8810/LAN8810i - GMII 10/100/1000 Ethernet Transceiver w/HP Auto-MDIX Support of devices. If you are using one of these devices please read the document located at [LAN8810/LAN8810i - GMII 10/100/1000 Ethernet Transceiver w/HP Auto-MDIX Support](#).

Notification Status: Final

Description of Change: 1) Updated bit 14 description of 10/100 Special Modes Register and clarified default value: 0 = Enable operational loopback 1 = Disable operational loopback* *Modern implementations of the MAC require this bit be set to 1b for 10BASE-T half duplex communication. Legacy implementation of the MAC may require this bit be set to 0b for 10BASE-T half duplex communication. This bit affects only 10BASE-T half duplex PHY mode. This bit may be set to either 0b or 1b with no affect on 10BASE-T full duplex, 100BASE-TX, or 1000BASE-T PHY operation.

Impacts to Data Sheet: None

Reason for Change: To Improve Manufacturability

Change Implementation Status: Complete

Date Document Changes Effective: 27 Apr 2018

NOTE: Please be advised that this is a change to the document only the product has not been changed.

Markings to Distinguish Revised from Unrevised Devices: N/A

Attachment(s):

[LAN8810/LAN8810i - GMII 10/100/1000 Ethernet Transceiver w/HP Auto-MDIX Support](#)

Please contact your local [Microchip sales office](#) with questions or concerns regarding this notification.

Terms and Conditions:

If you wish to change your product/process change notification (PCN) profile please log on to our website at microchip.com/PCN sign into myMICROCHIP to open the myMICROCHIP home page, then select a profile option from the left navigation bar.

To opt out of future offer or information emails (other than product change notification emails), click here to go to [microchip DIRECT](#) and login, then click on the "My account" link, click on "Update profile" and un-check the box that states "Future offers or information about Microchip's products or services."

Affected Catalog Part Numbers (CPN)

EVB-LAN8810

LAN8810-AKZE

LAN8810-AKZE-TR

LAN8810I-AKZE

LAN8810I-AKZE-TR