

## **PRODUCT DISCONTINUATION NOTICE**

PDN No.: USA2012/007

IXYS PRODUCT TYPE: IXTK250N10	<b>TYPE:</b> HIGH CUF	RRENT MOSFET	RECOMMEND REPLACEMENT: IXFK250N10P IXFK420N10T IXFK360N10T	
REASON FOR DISCONTINUATION:	WAFER MATERIAL TO	MANUFACTURE THIS	S DEVICE IS NO LONGER AVIALABLE.	
LAST TIME ORDER DATE:	N/A			
LAST TIME DELIVERY DATE:	N/A			
INTERNAL REFERENCE:				
INITIATOR GORDON ROSETE	TITLE/FUNCTION DEPT HEAD QA	DATE NOVEMBEF	E-MAIL R 14, 2012 G.ROSETE@IXYS.N	ET
CUSTOMER RESPONSE: (PLEASE FILL IN AND RETURN BY E-MAIL,	FAX OR MAIL WITHIN 4 WEEKS)			
for further questions/ inform	nation Comp	any:		
please comment		& Position		
	Phone	e / Fax No:		
COMMENTS:				
IF 0266 Rev.0 (01.26.10)	Page	1 of 1	Reference QS	0073