

Product Change Notification 32773 is complete and has been sent to approved customers. Please e-mail QA_PCN_SUPPORT@micron.com if you have any questions regarding this Product Change Notification.



Micron Technology, Inc.
8000 S. Federal Way
PO Box 6
Boise, ID United States

EOL of Select DRAM Components and Modules

PCN: 32773

Published: 2018-05-29

Revision History:

Revision 1, 2018/06/25: This document supersedes the original PCN #32773, dated 2018-05-29. Micron Part # MT48LC16M16A2B4-7E IT:G will continue to be supported and has been removed from the "Product Affected" section below.

Type:	End of Life
Description:	In an effort to maximize the manufacturing efficiency for Micron's DRAM product line, and to better align with industry trends, Micron will End of Life the below list of products. Micron is taking these actions to better focus efforts on supporting products that deliver the most value to our customers.
Reason:	Better Align With Industry Standard, Manufacturing Efficiency
Product Affected:	Select MPNs from multiple DRAM designs and process nodes

Affected Micron Part Number	Recommended Replacement	Customer Part Number
<u>Component</u>		
MT40A4G4HPR-075H:G	Contact Sales Representative	
MT40A512M8RH-075E:B	Contact Sales Representative	
MT40A8G4KVA-075H:G	Contact Sales Representative	

MT41K256M16TW-107 AT:P	Contact Sales Representative	
MT46V16M16P-5B IT:M	MT46V16M16P-5B XIT:M	
MT46V32M16CY-5B:J	Contact Sales Representative	
MT46V64M8P-5B IT:J	Contact Sales Representative	
MT48LC16M16A2B4-7E IT:G	MT48LC16M16A2B4-6A IT:G	
MT48LC2M32B2P-5:J	Contact Sales Representative	
MT48LC32M8A2P-6A IT:G	Contact Sales Representative	
MT48LC4M16A2B4-6A IT:J	Contact Sales Representative	
MT48LC4M32B2B5-6A IT:L	MT48LC4M32B2B5-6A XIT:L	
<u>Module</u>		
MT152KLS8G72M2Z-1G6N1B5	Contact Sales Representative	
MT16HTF51264HZ-800C1	Contact Sales Representative	
MT18HTF25672PDZ-80EM1	Contact Sales Representative	
MT18JDF1G72PDZ-1G9P1	Contact Sales Representative	
MT18KDF51272PZ-1G4K1	Contact Sales Representative	
MT18KSF51272PZ-1G6K1	Contact Sales Representative	
MT36HTF51272PZ-80EM1	Contact Sales Representative	
MT9JBF25672AKZ-1G4K2	Contact Sales Representative	
MT9KDF25672PZ-1G6K1	Contact Sales Representative	
MT9KDF51272AZ-1G6P1	Contact Sales Representative	
MT9KSF25672PZ-1G6K1	Contact Sales Representative	
MT9KSF51272HZ-1G6P1	Contact Sales Representative	
MTA144ASQ16G72LSZ-2S6G1	MTA144ASQ16G72LSZ-2S6E1	
MTA18ASF1G72PDZ-2G6B1	Contact Sales Representative	
MTA18ASF2G72PDZ-2G6H1	Contact Sales Representative	
MTA304ALS32G72M2SZ-1S6G1B5	MTA304ALS32G72M2SZ-1S6E1B5	
MTA36ASF4G72PZ-2G3B1C	Contact Sales Representative	
MTA608ALQ64G72M2SZ-1S6G1B5	MTA608ALQ64G72M2SZ-1S6E1B5	

*Materials that have been ordered are in **bold**.

Method of Identification:	Marketing Part Number
----------------------------------	-----------------------

Micron Sites Affected:	All Sites
-------------------------------	-----------

Last Purchase Date*:	2018-11-29
-----------------------------	------------

Last Shipment Date:	2019-05-29
----------------------------	------------

*Orders placed prior to the last purchase date are subject to current inventory levels, which may vary based on market conditions and customer demand. Early orders are encouraged.

NOTE: Per JEDEC Standard JESD46-C Section 3.2.3; lack of acknowledgment of this PCN within 30 days constitutes acceptance of change.

Micron Confidential and Proprietary Information

Legal Disclaimer: The information contained in this message may be privileged and confidential. It is intended to be read only by the individual or entity to whom it is addressed or by their designee. If the reader of this message is not the intended recipient, you are on notice that any distribution of this message, in any form, is strictly prohibited. If you have received this message in error, please immediately notify the sender and delete or destroy any copy of this message.