



Assembly Site Transfer for Parallel NOR Components from ASE Kunshan to ASE Shanghai

PCN: 33419

Published: 2020-04-06


Type: Manufacturing Site - Change or Addition, Product Mark/label Change

Description: In an effort to consolidate Micron's NOR assembly, Micron is transferring the following Parallel NOR components from ASE Kunshan, China to ASE Shanghai, China.

| Package | Qual Data Available | Sample Available | Product Ship Date |
|---------------------------|---------------------|------------------|-------------------|
| 64 ball LBGA 11x13x1.4 mm | 2020-04-15 | 2020-05-15 | 2020-11-15 |
| 56 ball VFBGA 7x9x1 mm | 2020-05-10 | 2020-06-30 | 2020-11-15 |
| 56 lead TSOP 14x20x1.2 mm | 2020-07-30 | 2020-08-30 | 2020-11-15 |

Note: During the transfer to ASE Shanghai assembly, Micron will add a 2D barcode to the **BGA** components for improved unit-level traceability. Please refer to page 6 in CSN-11: Product Marks/Product and Packaging Labels for component marking details.

SOP2/W-PDFN/BGA/LGA Abbreviated Component Mark



Assembly Site Locations:

- **Current:** ASE-KS: ASE Kunshan - No. 373, Songnan Road, Qiandeng, Kunshan, Jiangsu Province, 215341, P.R.C.
- **New:** ASE-SH - No. 669, Guoshoujing Road, Zhangjiang Hi-Tech Park, Pudong New Area, Shanghai 201203, P.R.C.

Reason: Manufacturing Efficiency, Supply Flexibility/Security

Product Affected: Parallel NOR 128Mb, 256Mb, 512Mb and 1Gb components

Affected Micron Part Number
 Component

Recommended Replacement

Customer Part Number

| | | |
|------------------------------|--|------------------|
| MT28EW01GABA1HJS-0AAT | | |
| MT28EW01GABA1HJS-0SIT | | ? |
| MT28EW01GABA1HPC-0AAT | | |
| MT28EW01GABA1HPC-0SIT | | 557-1993-2-ND, ? |
| MT28EW01GABA1LJS-0AAT | | 557-1830-2-ND |
| MT28EW01GABA1LJS-0SIT | | ? |
| MT28EW01GABA1LPC-0AAT | | 557-1831-2-ND |
| MT28EW01GABA1LPC-0SIT | | ? |
| MT28EW128ABA1HJS-0SIT | | 557-1776-ND, ? |
| MT28EW128ABA1HPC-0SIT | | ?, 557-1777-ND |
| MT28EW128ABA1HPN-0SIT | | 557-1994-2-ND |
| MT28EW128ABA1LJS-0SIT | | 557-1778-ND, ? |
| MT28EW128ABA1LPC-0SIT | | ?, 557-1779-ND |
| MT28EW128ABA1LPN-0SIT | | |
| MT28EW256ABA1HJS-0SIT | | ? |
| MT28EW256ABA1HPC-0SIT | | 557-1780-ND, ? |
| MT28EW256ABA1HPN-0SIT | | 557-1995-2-ND |
| MT28EW256ABA1LJS-0SIT | | 557-1781-ND, ? |
| MT28EW256ABA1LPC-0SIT | | ?, 557-1782-ND |
| MT28EW256ABA1LPN-0SIT | | |
| MT28EW512ABA1HJS-0AAT | | |
| MT28EW512ABA1HJS-0SIT | | ? |
| MT28EW512ABA1HPC-0AAT | | 557-1996-2-ND |
| MT28EW512ABA1HPC-0SIT | | ? |
| MT28EW512ABA1HPN-0SIT | | |
| MT28EW512ABA1LJS-0AAT | | |
| MT28EW512ABA1LJS-0SIT | | |
| MT28EW512ABA1LPC-0AAT | | 557-2025-ND |
| MT28EW512ABA1LPC-0SIT | | ? |
| MT28EW512ABA1LPN-0SIT | | |
| MT28FW01GABA1HJS-0AAT | | |
| MT28FW01GABA1HPC-0AAT | | |
| MT28FW01GABA1LJS-0AAT | | |
| MT28FW01GABA1LPC-0AAT | | |
| MT28FW512ABA1HJS-0AAT | | |
| MT28FW512ABA1HPC-0AAT | | |
| MT28FW512ABA1LJS-0AAT | | |
| MT28FW512ABA1LPC-0AAT | | |

*Materials that have been ordered are in **bold**.

| | |
|----------------------------------|---|
| Method of Identification: | Please refer to Micron's Customer Service Note - Product Marks, Product Labels, and Packaging Labels CSN-11 for details on Product Marks and Labels specific to the codes for countries of encapsulation. |
| Micron Sites Affected: | Subcontractor |
| Sample Available: | 2020-05-15 |
| Qual Data Available: | 2020-04-15 |
| Product Ship Date: | 2020-11-15 |

NOTE: Per JEDEC Standard JESD46-C Section 3.2.3; lack of acknowledgment of this PCN within 30 days constitutes acceptance of change.

Micron Confidential and Proprietary Information

Attachments

There are no attachments on this PCN