



## Product Change Notice

Micron PCN: 31519

Date: 4/23/2015

<b>Type of Change:</b>	End of Life	
<b>Title of Change:</b>	EOL of Select SDR/DDR/DDR2/DDR3 SDRAM and RLDRAM 3 Parts	
<b>Description of Change:</b>	Micron is announcing the EOL of select MPNs to consolidate our portfolio and improve manufacturing efficiency	
<b>Reason for Change:</b>	Manufacturing Efficiency	
<b>Contact Information:</b>	<u>Marketing Contact</u> DRAM MARKETING Micron Semiconductor Prds <a href="mailto:DRAM_MARKETING@MICRON.COM">DRAM_MARKETING@MICRON.COM</a>	<u>Engineering Contact</u> DRAM SUPPORT Micron Semiconductor Prds <a href="mailto:DRAMSUPPORT@MICRON.COM">DRAMSUPPORT@MICRON.COM</a>

**Product Affected:** Select MPNs from multiple designs and process nodes

<b>Affected Micron Part Number</b>	<b>Suggested Replacement Part</b>
<b>RLDRAM 3</b>	
MT44K32M18RB-093:A	MT44K32M18RB-093E:A
MT44K16M36RB-093:A	MT44K16M36RB-093E:A
<b>DDR SDRAM</b>	
MT46V32M8P-5B IT:M	Contact Factory
MT46V128M4P-5B:J	Contact Factory
MT46V32M16P-5B L:J	Contact Factory
MT46V32M16CY-5B L IT:J	Contact Factory
<b>DDR2 SDRAM</b>	
<b>Components</b>	
MT47H256M8EB-187E:C	MT47H256M8EB-25E:C
MT47H512M4EB-3:C	MT47H512M4EB-25E:C
MT47H128M16RT-3:C	MT47H128M16RT-25E:C
MT47H128M16RT-187E:C	MT47H128M16RT-25E:C
<b>Modules</b>	
MT18HTF51272PDZ-80EC1	MT36HTF51272PZ-80EM1
MT36HTF1G72FZ-80EC1D6	MT72HTS1G72FZ-80EM1D6
<b>DDR3 SDRAM</b>	
<b>Components</b>	
MT41K512M8RH-125 M:E	Contact Factory
MT41K2G4TRF-15E:E	MT41K2G4TRF-125:E
MT41J512M8RH-125:E	MT41K512M8RH-125:E
MT41K256M16HA-107 M:E	Contact Factory
MT41K256M8DA-125 M:K	Contact Factory



---

<b>Affected Micron Part Number</b>	<b>Suggested Replacement Part</b>
<b>DDR3 SDRAM</b>	
<b>Modules</b>	
MT16KTF1G64AZ-1G4E1	MT16KTF1G64AZ-1G6E1
MT18JDF1G72AZ-1G6E1	MT18KDF1G72AZ-1G6E1
MT18JSF1G72AZ-1G9E1	MT18JSF1G72AZ-1G9E3
MT4MTF25664HZ-1G6E1	MT4KTF25664HZ-1G6E1
MT8KTF51264HZ-1G4E1	Contact Factory
MT8MTF51264HZ-1G6E1	Contact Factory
MT9JSF51272PZ-1G6E1	MT18KSF51272PZ-1G6K1
MT9KBF51272AKIZ-1G4E1	MT18KSF51272PZ-1G6K1
MT9KSF51272PZ-1G4E1	MT4KTF25664HZ-1G6E1
MT16MTF1G64HZ-1G6E1	MT16KTF1G64HZ-1G6N1
MT18KSF1G72PKIZ-1G4E1	MT18KBZS1G72PKIZ-1G4E1
MT18JSF51272AKZ-1G4K1	MT9KSF51272AKZ-1G4E1
MT16KTF51264AZ-1G4K1	MT8KTF51264AZ-1G6E1
MT16JTF51264AZ-1G6K1	MT8KTF51264AZ-1G6E1
MT8KTF25664HDZ-1G4K1	MT8KTF25664HZ-1G6K1
MT4KTF12864HZ-1G4K1	MT4KTF12864HZ-1G6K1
MT16KTF51264HZ-1G4K1	MT16KTF51264HZ-1G6K1
MT18JSF51272PDZ-1G9K1	MT18JSF51272PZ-1G9K1
MT9JSF25672PZ-1G9K1	MT18JSF51272PZ-1G9K1
MT4JTF12864HZ-1G4K1	MT4KTF12864HZ-1G6K1
MT8JTF25664AZ-1G6K1	MT4KTF25664AZ-1G6E1
MT18JDF51272PZ-1G6K1	MT18KDF51272PDZ-1G6K1
MT9JSF25672AZ-2G1K1	Contact Factory
MT18KDF51272PTZ-1G6K1	Contact Factory
MT18KSF51272HZ-1G4K2	MT18KSF51272HZ-1G6K2
MT18JDF51272PZ-1G9K2	MT18JDF51272PDZ-1G9K2
MT9JBF25672AKIZ-1G4K2	MT9JBF25672AKIZ-1G4K1
MT9KDF25672AZ-1G4K1	MT18KDF51272AZ-1G4K1
MT18JSF51272PKZ-1G4K1	MT9KBZF51272PKIZ-1G4E1
MT18JSF51272PKIZ-1G4K1	MT9KBZF51272PKIZ-1G4E1



---

<b>Affected Micron Part Number</b>	<b>Suggested Replacement Part</b>
<b>SDRAM</b>	
MT48LC4M16A2B4-7E:J	Contact Factory
MT48LC16M8A2BB-6A:L	Contact Factory
MT48LC16M8A2P-7E:L	Contact Factory
MT48LC16M16A2P-6A L:G	Contact Factory
MT48LC64M4A2P-7E:G	Contact Factory
MT48LC32M8A2BB-6A:G	Contact Factory
MT48LC32M8A2BB-7E:G	Contact Factory

---

**Micron Sites Affected:** All Sites

---

**Product/Data Schedule**

**Current/Discontinued Product:**

Last Purchase Date\*: 23-Oct-2015

Last Shipment Date: 23-Apr-2016

---

\*Orders placed prior to the last purchase date are subject to current inventory levels, which may vary based on market conditions and customer demand. Early orders are encouraged.